

Aruba Instant On 1830 Switch Series Release Notes

Version 2.6.0.75



Copyright Information

© Copyright 2022 Hewlett Packard Enterprise Development LP.

Open Source Code

This product includes code licensed under the GNU General Public License, the GNU Lesser General Public License, and/or certain other open source licenses. A complete machine-readable copy of the source code corresponding to such code is available upon request. This offer is valid to anyone in receipt of this information and shall expire three years following the date of the final distribution of this product version by Hewlett Packard Enterprise Company. To obtain such source code, send a check or money order in the amount of US \$10.00 to:

Hewlett Packard Enterprise Company
6280 America Center Drive
San Jose, CA 95002
USA

Notices

The information contained herein is subject to change without notice. The only warranties for Hewlett Packard Enterprise products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. Hewlett Packard Enterprise shall not be liable for technical or editorial errors or omissions contained herein.

Confidential computer software. Valid license from Hewlett Packard Enterprise required for possession, use, or copying. Consistent with FAR 12.211 and 12.212, Commercial Computer Software, Computer Software Documentation, and Technical Data for Commercial Items are licensed to the U.S. Government under vendor's standard commercial license.

Links to third-party websites take you outside the Hewlett Packard Enterprise website. Hewlett Packard Enterprise has no control over and is not responsible for information outside the Hewlett Packard Enterprise website.

Acknowledgments

All third-party marks are property of their respective owners.

Description

This release note covers software versions for the 2.0 branch of the software. Version 2.6.0.75 is the third release of major version 2.0.

Product series supported by this software:

- Aruba Instant On 1830 Switch Series

Important Information

To avoid damage to your equipment, do not interrupt power to the switch during a software update. Aruba recommends always updating to the latest version of software to ensure the best performance for your switch.

Version History

All released versions are fully supported by Aruba, unless noted in the table.

Version number	Release date	Remarks
2.6.0.75	2022-11-09	Released, fully supported, and posted to the web.
2.6.0.73	2022-06-23	Released, fully supported, and posted to the web.
2.5.0.48	2022-02-07	Released, fully supported, and posted to the web.
2.5.0.45	2022-02-07	Initial 2.0 release of the Aruba Instant On 1830 software. Released, fully supported, and posted to the web.

Products Supported

This release applies to the following product models:

Product number	Description
JL810A	Aruba Instant On 1830 8G Switch
JL811A	Aruba Instant On 1830 8G 4p Class4 PoE 65W Switch
JL812A	Aruba Instant On 1830 24G 2SFP Switch

Product number	Description
JL813A	Aruba Instant On 1830 24G 12p Class4 PoE 2SFP 195W Switch
JL814A	Aruba Instant On 1830 48G 4SFP Switch
JL815A	Aruba Instant On 1830 48G 24p Class4 PoE 4SFP 370W Switch

Compatibility/Interoperability

The switch web agent supports the following web browsers:

Operating system	Browser
Windows 7	Chrome version 87 or higher Firefox version 84 or higher
Windows 10	Chrome version 87 or higher Firefox version 84 or higher
Mac OS X 10.15	Safari version 14 or higher Chrome version 87 or higher Firefox version 84 or higher
Linux OS 2.6, 3.11	Chrome version 87 or higher Firefox version 84 or higher



Aruba recommends using the most recent version of each browser as of the date of this release note.

Enhancements

This section lists released builds that include enhancements found in this branch of the software. Software enhancements are listed in reverse-chronological order, with the newest on the top of the list. Unless otherwise noted, each software version listed includes all enhancements added in earlier versions.

Version 2.6.0.75

Type	Description
Hardware	Added support for new memory components.

Version 2.6.0.73

There are no enhancements introduced in this release.

Version 2.5.0.48

There are no enhancements introduced in this release.

Version 2.5.0.45

Initial release of the Aruba Instant On 1830 software. Released, fully supported, and posted to the web.

Fixes

This section lists released builds that include fixes found in this branch of the software. Software fixes are listed in reverse-chronological order, with the newest on the top of the list. Unless otherwise noted, each software version listed includes all fixes added in earlier versions.

The Symptom statement describes what a user might experience if this is seen on the network. The Scenario statement provides additional environment details and trigger summaries. When available, the Workaround statement provides a workaround to the issue for customers who decide not to update to this version of software.



The Bug ID is used for tracking purposes.

Version 2.6.0.75

There are no new resolved issues in this release.

Version 2.6.0.73

Type	Bug ID	Description
Spanning Tree Protocol	26073-0002	Symptom/Scenario: Loops may occur on the network when the TCN (Topology Change Notification) feature is enabled on all switch ports. Workaround: Disable TCN Guard.
WebUI	26073-0001	Symptom/Scenario: The SFP/SFP+ ports tool tip is missing from the graphical Device Image. Workaround: Navigate to the Port Configuration or Event log to identify the transceiver type.

Version 2.5.0.48

Type	Bug ID	Description
LEDs	25045-001	Symptom/Scenario: Pressing the external reset pin for more than 5 seconds should turn on the front panel LEDs. Workaround: Not required. Factory reset will occur after pressing the external reset pin for more than 5 seconds.
EEE	25045-002	Symptom/Scenario: EEE is disabled by default instead of enabled. Workaround: Manually enable EEE.
User Accounts	25045-003	Symptom/Scenario: Password lockout feature is enabled by default instead of disabled. Workaround: Manually disable the Password Lockout feature.

Version 2.5.0.45

Initial release of the Aruba Instant On 1830 software. Released, fully supported, and posted to the web.

Issues and Workarounds

Version 2.6.0.75

There are no new known issues in this release.

Version 2.6.0.73

Type	Bug ID	Description
Diagnostics	26073-0003	Symptom/Scenario: The Ping Interval time setting is labeled incorrectly as Timeout. Workaround: None.
SNMP	26073-0004	Symptom/Scenario: If the SNMP engine ID field is manually deleted from the Configuration file, an invalid value will be displayed in the webUI. Workaround: Factory reset will regenerate and properly display a unique SNMP engine ID.
VLAN	26073-0005	Symptom/Scenario: VLAN Interface Configuration does not update the ports PVID value when added to a VLAN with untagged membership. Workaround: Modify the port VID manually to match the VLAN in which the port was included.

Version 2.5.0.48

Type	Bug ID	Description
Web UI	25045-004	Symptom/Scenario: The SFP+ ports tool tip is missing from the graphical device Image. Workaround: Navigate to the Port Configuration or Event log to identify the transceiver type.
HTTP	25045-005	Symptom/Scenario: HTTP soft session timeout may fail when using non-default values. Workaround: Utilize the default value (10 minutes).

Version 2.5.0.45

Type	Bug ID	Description
LEDs	25045-001	Symptom/Scenario: Pressing the external reset pin for more than 5 seconds should turn on the front panel LEDs. Workaround: Not required. Factory reset will occur after pressing the external reset pin for more than 5 seconds.
EEE	25045-002	Symptom/Scenario: EEE is disabled by default instead of enabled. Workaround: Manually enable EEE.
User Accounts	25045-003	Symptom/Scenario: Password lockout feature is enabled by default instead of disabled. Workaround: Manually disable the Password Lockout feature.
Web UI	25045-004	Symptom/Scenario: The SFP+ ports tool tip is missing from the graphical device Image.

Type	Bug ID	Description
		Workaround: Navigate to the Port Configuration or Event log to identify the transceiver type.
HTTP	25045-005	Symptom/Scenario: HTTP soft session timeout may fail when using non-default values. Workaround: Utilize the default value (10 minutes).

Contacting Support

Main site	https://www.arubainstanton.com/
Support site	https://support.arubainstanton.com/
Social forums and knowledge base	https://community.arubainstanton.com/
Telephone	https://www.arubainstanton.com/contact-support/
EULA	https://www.arubainstanton.com/eula/
Security	https://www.arubanetworks.com/support-services/security-bulletins/ Email: mailto: aruba-sirt@hpe.com